

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC4275) was tested in accordance with the Road Safety (General) Regulations 2019 on the 20/07/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.




Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

CERTIFICATE UNDER SECTION 83
ROAD SAFETY ACT 1986

The road safety camera (No. SDC5277) was tested in accordance with the Road Safety (General) Regulations 2009 on the 01/08/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

Road Safety (General) Regulations 2009

S.R. No. 115/2009

SCHEDULE 3

Regulation 52, 65


CERTIFICATE UNDER SECTION 83

The * road safety camera/~~*speed detector~~ /~~*portable weighing device~~ (No. SDC 4504) was tested in accordance with the Road Safety (General) Regulations 2009 on the

.....06 September 2016..... (date).

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations.

The device has been properly sealed in accordance with those Regulations.



* Strike out whichever is not applicable.

** of the school of electrical engineering at,

ROYAL MELBOURNE INSTITUTE OF TECHNOLOGY

being a

University in Victoria
