

SCHEDULE 2

Regulation 6(3)

CERTIFICATE UNDER SECTION 78A



I am a licensed surveyor within the meaning of the **Surveying Act 2004** and I am approved by the Surveyor-General for the purposes of section 78A of the **Road Safety Act 1986**.

I certify that the shortest distance, expressed in metres, that would be travelled by a motor vehicle on the northbound carriageway of the Peninsula Link Freeway between:

- (a) the vehicle detectors at 20 metres South of Loders Road Bridge, Moorooduc and
 - (b) the vehicle detectors at 16 metres South of Eramosa Rd West Bridge, Moorooduc,
- is 5,632 metres.

Signature of person issuing certificate:



Name:  Licensed Surveyor Registration No. 

Date: 21 June 2013

SCHEDULE 2

Regulation 6(3)

CERTIFICATE UNDER SECTION 78A



I am a licensed surveyor within the meaning of the **Surveying Act 2004** and I am approved by the Surveyor-General for the purposes of section 78A of the **Road Safety Act 1986**.

I certify that the shortest distance, expressed in metres, that would be travelled by a motor vehicle on the northbound carriageway of the Peninsula Link Freeway between:

(a) the vehicle detectors at 16 metres South of Eramosa Rd West Bridge, Moorooduc and

(a) the vehicle detectors at 10 metres South of Skye Road Bridge, Frankston and is 9,576 metres.

Signature of person issuing certificate:

Name:  Licensed Surveyor Registration No. 

Date: 19 June 2013


CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC5262) was tested in accordance with the Road Safety (General) Regulations 2019 on the 03/02/2021.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

SCHEDULE 3

Regulation 51

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC5251) was tested in accordance with the Road Safety (General) Regulations 2019 on the 04/02/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. SDC4957) was tested in accordance with the Road Safety (General) Regulations 2009 on the 04/02/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748