


**CERTIFICATE UNDER SECTION 83
ROAD SAFETY ACT 1986**

The road safety camera DRCS-P 0071 (DCU No. 0428 Antenna No.0595) was tested in accordance with the Road Safety (General) Regulations 2019 on the 17/02/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0069 (DCU No. 0434 Antenna No.0444) was tested in accordance with the Road Safety (General) Regulations 2019 on the 17/02/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

CERTIFICATE UNDER SECTION 83
ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0010 (DCU No. 0499 Antenna No.0445) was tested in accordance with the Road Safety (General) Regulations 2019 on the 17/02/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

SCHEDULE 3

Regulation 51



CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0044 (DCU No. 0498 Antenna No.0593) was tested in accordance with the Road Safety (General) Regulations 2019 on the 17/02/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0071 (DCU No. 0428 Antenna No.0595) was tested in accordance with the Road Safety (General) Regulations 2009 on the 18/02/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0069 (DCU No. 0434 Antenna No.0444) was tested in accordance with the Road Safety (General) Regulations 2009 on the 18/02/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

SCHEDULE 3


Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0010 (DCU No. 0499 Antenna No.0445) was tested in accordance with the Road Safety (General) Regulations 2009 on the 18/02/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

SCHEDULE 3




Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0044 (DCU No. 0217 Antenna No.0593) was tested in accordance with the Road Safety (General) Regulations 2009 on the 18/02/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.






Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

CERTIFICATE UNDER SECTION 83
ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0069 (DCU No. 0434 Antenna No.0444) was tested in accordance with the Road Safety (General) Regulations 2009 on the 16/02/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748



SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83
ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0069 (DCU No. 0434 Antenna No.0444) was tested in accordance with the Road Safety (General) Regulations 2009 on the 16/02/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera DRCS-P 0010 (DCU No. 0499 Antenna No.0445) was tested in accordance with the Road Safety (General) Regulations 2009 on the 16/02/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

SCHEDULE 3

Regulation 52

CERTIFICATE UNDER SECTION 83**ROAD SAFETY ACT 1986**

The road safety camera DRCS-P 0044 (DCU No. 0217 Antenna No.0593) was tested in accordance with the Road Safety (General) Regulations 2009 on the 16/02/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748