

**SCHEDULE 3**

**Regulation 51**

**CERTIFICATE UNDER SECTION 83**

**ROAD SAFETY ACT 1986**

The road safety camera (No. 593-071/71007) was tested in accordance with the Road Safety (General) Regulations 2019 on the 18/09/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)

**CERTIFICATE UNDER SECTION 83**

**ROAD SAFETY ACT 1986**

The road safety camera (No. 593-071/71235) was tested in accordance with the Road Safety (General) Regulations 2009 on the 18/09/2019.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748

**CERTIFICATE UNDER SECTION 83**

**ROAD SAFETY ACT 1986**

The road safety camera (No. 593-071/60082) was tested in accordance with the Road Safety (General) Regulations 2009 on the 17/09/2018.

The test confirmed that the device was operating correctly in accordance with the requirements of those Regulations. The device has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a testing body accredited in the field of electrical testing by the National Association of Testing Authorities, Australia (NATA) ACN 004 379 748