

SCHEDULE 3

Regulation 51


CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. A008606) was tested in accordance with the Road Safety (General) Regulations 2019 on the 23/03/2021.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)


CERTIFICATE UNDER SECTION 83

ROAD SAFETY ACT 1986

The road safety camera (No. A008606) was tested in accordance with the Road Safety (General) Regulations 2019 on the 25/03/2020.

The test confirmed that the road safety camera was operating correctly in accordance with the requirements of those Regulations.

The road safety camera has been properly sealed in accordance with those Regulations.



Testing Officer, SGS Australia Pty Ltd, a facility accredited in the testing and calibration of speed detectors or road safety cameras by the National Association of Testing Authorities, Australia (NATA)